Appendix B -1
Aerial Photographs of Tribal Development Projects
Flight Date: June 13, 2001




Plate 1: View of Viejas Casino and Turf Club and Viejas Outlet Center Facilities looking northeast.




Plate 2: View of Viejas Facilities looking due east.



Plate 3: View of Southern Indian Health Clinic Facility on Willows Road, looking northwest.




Plate 4: View of Viejas Facilities looking due north with westbound Interstate 8 in foreground.



Plate 5: View of the Southern Indian Health Clinic from the southwest.



Plate 6: View of Southern Indian Health Clinic from the southwest.




Plate 7: View of the Interstate 8/Willows Road interchange looking east.



Plate 8: View of the Sycuan Casino looking southeast.




Plate 9: View of the Sycuan Casino looking due north.




Plate 10: View of the Sycuan Casino looking southeast.




Plate 11: View of the Sycuan Casino looking south.




Plate 12: View of the Sycuan Casino looking southwest.



Plate 13: View of the Jamul Indian Village looking northwest.




Plate 14: View of the Jamul Indian Village looking east.



Plate 15: View of the Jamul Indian Village looking west with State Route 94 in the foreground.



Plate 16: View of the Barona Casino looking north.



Plate 17: New facilities under construction at the Barona Casino.



Plate 18: View of the Barona Casino looking southwest.




Plate 19: View of the Barona Casino looking west.



Plate 20: View of the Pala Casino looking northeast. Water feature is the San Luis Rey River.



Plate 21: View of the Pala Casino looking southeast.




Plate 22: View of the Pala Casino looking south.




Plate 23: Close-up view of the Pala Casino looking north across the San Luis Rey River.



Plate 24: View of Casino Pauma looking southeast.



Plate 25: View of Casino Pauma looking due east.



Plate 26: View of the Rincon Casino looking west.




Plate 27: View of the Rincon Casino looking north.




Plate 28: View of the Valley View Casino on the San Pasqual Reservation looking west.



Plate 29: View of the Valley View Casino on the San Pasqual Reservation looking northeast.



Plate 30: View of the Valley View Casino on the San Pasqual Reservation looking west.




Plate 31: View of the La Jolla Indian Reservation Water Park.



Plate 32: View of the Off-road Track at the La Jolla Indian Reservation.



Plate 33: View of the construction/grading activities associated with the Casino/Travel Center on the Campo Indian Reservation looking northwest.




Plate 34: View of the Casino/Truck Stop facilities on the Campo Indian Reservation looking east above the intersection of I-8 and Old Hwy 80.




Plate 35: View of the existing sand mining operation on the La Posta Indian Reservation.